


MFD 1

GNS 430



NOTE 1 : These connections are for redundancy in case of loss of MFD 1, normally supplied from inter-display communications.

Document Version History

WD-1003-01 First released version.

WD-1003-02 Corrected document name WD-1001-04 to WD-1003-02.

Removed MFD-2 PIN A-20 from MFD-1 C-5.

The ARINC-429 connection between the GTX330 and GNS430 is now shown for clarification.